

HRE4 - Heat synergy regions

- Excess heat (E) vs. heat demand (Q)
- by NUTS3 region
- Priority groups
- Romania

Priority group 1 (very high)

■ E & Q > 10 PJ/a

No priority

□ E_{max} < 2.5 PJ/a; Q_{max} < 25 PJ/a

Priority group 2 (high)

■ 1 PJ/a < E < 10 PJ/a; Q > 10 PJ/a

■ NUTS3 regions; No excess heat data

□ Countries - HRE4

Priority group 3 (moderate)

■ E > 10 PJ/a; 1 PJ/a < Q < 10 PJ/a

□ Countries - EU28

Priority group 4 (low)

□ 1 < E & Q < 10 PJ/a

